

FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12

IMPROVED KEYBOARD SUPPORT MECHANISM

George Mileos,

Appln. No.: 09/357,175




FIG. 13

IMPROVED KEYBOARD SUPPORT MECHANISM  
George Mileos, Appln. No.: 09/357,175




FIG. 15




FIG. 16

IMPROVED KEYBOARD SUPPORT MECHANISM

George Mileos,

Appln. No.: 09/357,175




FIG. 18




FIG. 19

## IMPROVED KEYBOARD SUPPORT MECHANISM

George Mileos,

Appln. No.: 09/357,175




FIG. 20

IMPROVED KEYBOARD SUPPORT MECHANISM  
George Mileos, Appln. No.: 09/357,175